


Aangemaakt: 15-02-2021

Remote Inspections drones & RO



David Knukkel
Julianalaan 67A
2628 BC NL

info@drone-
inspection.global
www.drone-
inspection.global
+31629022439


De Challenge

Safe and cost efficient inspections of assets at heights, under water and/or enclosed spaces. Consequential damage of scaffolding operations in tanks

De Solution

Remote inspection of enclosed spaces and areas hard to reach (either at height or under water) by UAV's and/or ROV's, avoiding scaffolding, rafting, rope access, divers and enclosed space entries

Image not found or type unknown



De Businesscase

Valuation of safety is difficult and varies per client. Time efficiency: average visual inspection time of a storage tank 2 hours with one pilot and assistant against two days scaffolding building/removal and half a day by a team of rope access.